




Contract No. 83656




ITEM NO.	IDENTIFICATION
1	OUTLET BOX - GALV. 21 CU.IN. (0.000344 CU-M)
2	LAMP HOLDER AND COVER
3	OUTLET BOX COVER
4	RUBBER COVER GASKET
5	REDUCING BUSHING
6	1/4" (19 mm) CLOSE NIPPLE
7	1/4" (19 mm) LOCKNUT
8	1/4" (19 mm) HOLE PLUG
9	SADDLE BRACKET - GALV.
10	PAR 38 LAMP
11	DETECTOR UNIT
12	POST CAP [18 FT. (5.4 m) POST MIN.]

NOTES

1. ALL ELECTRICAL ITEMS, EXCEPT ITEM #2 AND #11 SHALL BE ALUMINUM OR GALVANIZED.
2. ITEM #1- ZUG/GEDNEY FSX-1-50 OR EQUIVALENT.
ITEM #2- MULBERRY CON-O-SHADE LAMP SHIELD OR EQUIVALENT.
ITEM #9- "BAND-IT" SADDLE BRACKET OR EQUIVALENT
3. WHEN POST MOUNTING IS SPECIFIED, ITEM #9 SHALL NOT BE REQUIRED. THE DETECTION UNIT SHALL BE MOUNTED DIRECTLY ON TOP OF THE CAP BY DRILLING AND TAPPING A 3/4" (19 mm) HOLE WITH PIPE THREADS. THE POST CAP SHALL EITHER BE SCREWED TO THE TOP OF THE POST OR A MINIMUM OF 3 TIGHTING SCREWS SHALL BE REQUIRED ON EACH CAP.

© 2012 Blackwell Publishing Ltd *Journal of Internal Medicine* 272: 103–111



REVISIONS	
NAME	DATE

 Lake County Division of Transportation	
TRAFFIC SIGNAL STANDARD DETAIL-2	
BUFFALO GROVE ROAD AT PORT CLINTON ROAD	
SCALE: NONE	DRAWN BY: L.S.
DATE: 04/15/04	CHECKED BY: ADG

P:\projects\01600\ETraffic\Sheet\TS05-STD2.dgn
04/15/2004
08:44:17 AM